COMMANDER AMPHIBIOUS GROUP THREE INSTRUCTION 4730.1C

Subj: PREPARATION FOR INSPECTION BY THE BOARD OF INSPECTION AND SURVEY (INSURV)

Ref: (a) COMNAVSURFLANT/PAC MSG 301728Z Aug 01

- (b) COMNAVSURFPACINST 5400.1 (Series)
- (c) INSURVINST 4730.1B (Series)
- (d) COMNAVSURFPACINST 4700.1 (series)
- (e) CINCPACFLTINST 4790.3 (Series)

Encl: (1) INSURV Milestones

- (2) Sample Quick Look Follow Up Message Format
- 1. <u>Purpose</u>. To promulgate additional guidance to assist Amphibious Group THREE ships in preparing for Material Inspection (MI) conducted by the Board of Inspection and Survey.
- 2. Cancellation. COMPIBGRUTHREEINST 4730.1B
- 3. <u>Scope</u>. This instruction provides guidance for INSURV Material Inspections preparation. Enclosure (1) provides a sample Milestone Listing. Enclosure (2) incorporates the post-INSURV report.

4. Action

- a. This instruction shall be used as guidance to help prepare for the conduct of INSURV MI Inspection. The intention is not to establish examination standards but to provide additional guidance for inspection areas using standards already provided in references (a) through (e). Nothing in this instruction should be construed as superseding, modifying, or constituting authority to make changes to U.S. Navy Regulations, manuals, and instructions concerning inspections conducted by the Board of Inspection and Survey, which govern the construction, testing, operation, and maintenance of COMPHIBGRU THREE ships.
- b. All ships in COMPHIBGRU THREE shall incorporate milestones listed in enclosure (1) in their own POA&M's developed six months prior and shall be implemented not later than 16 weeks prior to the INSURV date. Enclosure (1) is not

all-inclusive and feedback to COMPHIBGRU THREE for this instruction is encouraged.

- c. COMPHIBGRU THREE (N4) will contact the ship's INSURV Coordinator to establish a date for the ISIC pre-INSURV assist. This is a two-day evolution and is intended to provide a fresh set of eyes in identifying discrepancies for documentation about one to two months before the INSURV.
- 5. Report. Written reports except as addressed in enclosure (2) are not required. However, a brief by the ship's Commanding Officer to COMPHIBGRU THREE will be scheduled approximately 4-8 weeks prior to the INSURV.
 - a. The Commanding Officer's brief should include:
- (1) Progress of ship to date in preparing for the inspection/trial, using reference (a) and enclosure (1) as a guide.
- (2) Material problems and significant discrepancies which will probably result in mission degrades by the INSURV Board.
- (3) Any assistance the ship may require from COMPHIBGRU THREE or other activities.
- b. Within two weeks of the completion of INSURV a one-time report addressing those discrepancies listed in the INSURV quick look is to be sent by message. Enclosure (2) provides guidance on the format and items to be addressed in this follow-up report.

K. E. GOLDEN
Chief of Staff
Acting

Distribution:
COMPHIBGRTHREEINST 5216.1Z
List 1 through 5 (Case I)

INS	URV MILESTONES		
		OPENING DATE: 16 weeks before INS	 SUR
BAC	KGROUND:		
OPN OPN	MAVINST 5420.70 (Series) MAVINST 4700.8 (Series) MAVINST 4730.55 (Series) MAVINST C3501.2 (Series) MAVINST 4730.1B	COMNAVSURFPACINST 4700.1 (Series COMNAVSURFPACINST 5400.1 (Series	
	REMARKS/ACTION	SKED ACTUAL	
1.	Publish POA&M for INSUR INSURV)	RV (At least 16 weeks before SKED	
2.	Designate experienced O	Officer as single shipwide INSURV	
3.	Review PMS Checks.		
4.	Review tag out guide li	sts to ensure signatures are curren	nt.

REMARKS/ACTION	SKED	ACTUAL				
5. Review and update CMSP for o	correct documentat	tion.				
6. Receive a pre-INSURV assessment by ISIC (approx 1-2 months prior to INSURV).						
7. Acquire all above instruction	ons.					
8. Receive advance preparation package from INSURVE Board (Ref: INSURVINST 4730.1B INSURV - 60 days)						
		_				
9. Schedule key shipboard personship.	onnel to observe N	MI on another				
10. Liaison with the INSURV Boaseries). NOTE: Each Trial/Inspect a recorder whose duties include OF CONTACT for liaison with the any aspect of the trial/inspectito ensure a complete comprehensi	ection, the Board acting as the Boas ship. Questions on can be resolve	assigns ard's POINT regarding ed early on				
11. Brief of COMPHIBGRUTHREE by approximately 4-6 weeks before I	-	ng Office				

COMPHIBGRTHREEINST 4730.1C

	REMARKS/ACTION	SKED	ACTUAL
of tagen	Provide a proposed agenda he trial/inspection per gu da to board at least 30 da RVINST 4730.1B (Series)).	idelines of	Appendix A. Submit
	Fill out and prepare defi.11J (Series).	ciency forms	per INSURVINST
	Collect documents, recordies). Board to review upo		listed in 4730.1B
·			
	Arrange for outside assis nstrations as discussed IN		-
	Complete preparations lis	ted in each	Appendix of INSURIVNST
17. Encl	Submit INSURV follow-up rosure (2).	eport to COM	PHIBGRTHREE per

INSURV FOLLOW UP-REPORT

- 1. Answer the following questions for each discrepancy listed in the INSURV Quick Look message:
- a. Provide an explanation for discrepancy (e.g., equipment casualty, personnel error, design deficiency, inadequate OPTAR funding to fill shortage, equipment, material on order, etc.).
 - b. Is it a class/Navy-wide problem or is it ship-specific?
- c. If ship-specific, was it identified and documented prior to INSURV? Some ways of documenting are CASREP, CSMP, AER/SA (REQ), SFWL, etc.) If item is multiple deficiency (e.g., 6 of 24 widgets were INOP) how many were known and documented prior to INSURV?
- d. If deficiency is result of INSURV making call using standards other than those the ship used, briefly address (e.g., of 10 HF transmitters found degraded, 5 passed PMS standards but INSURV used different standards). Provide separate message/letter amplification so differences in standards may be addressed to INSURV board.
- 2. In covering the inspection areas, use same format as Quick Look Report:
 - a. Engineering
 - (1) Main propulsion
 - (2) Boilers
 - b. Damage Control
 - (1) Firefighting
 - (2) CBR/Watertight Integrity
 - c. Combat Systems
 - d. Deck

COMPHIBGRUTHREEINST 4730.1C

- e. Aviation
- f. Supply
- q. Environmental Protection
- h. Medical
- i. Habitability
- 3. Sample INSURV Follow Up Message:

FM: USS SAMPLE

TO: COMPHIBGRU THREE//N01/N4/N43//

INFO: COMNAVSURFPAC SAN DIEGO CA//N00/N01/N6/N8/N43//

BT

C O N F I D E N T I A L //N04730//

MSGID/GENADMIN/(SHIP)//

SUBJ/INSURV FOLLOW UP REPORT (U)//

REF/A/MSG/USS GATOR/012040ZJAN99/-/NOTAL//

REFB/DOC/COMPHIBGRUTHREEINST 4730.1B//

NARR/(U) REF A IS A QUICK LOOK RPT FOR USS GATOR UMI AND REF B IS COMPHIBGRUTHREEINST INSURV INSTRUCTION.//

RMKS/1. (C) FOL INFO IS PROVIDED FOR EACH DISCREPANCY NOTED IN REF A:

- A. ENGINEERING
 - (1) MAIN PROPULSION

(CLASSIFIED MARKING FOR ILLUSTRATION PURPOSES ONLY)

COMPHIBGRUTHREEINST 4730.1

FULL POWER UNSAT

- (A) CAUSE OF UNSAT FULLL POWER WAS HIGH BEARING TEMP ON ONE FDB (CORRECTED). LUBE OIL COOLER ON FDB WAS FOULED WITH MARINE GROWTH.
 - (B) SHIP-SPECIFIC.
 - (C) NOT ID PRIOR.
 - (D) N/A
- AFT EMERGENCY FEED PUMP WOULD NOT MAINTAIN BOILER WATER DURING AUX STEAMING.
 - (A) PUMP OUT OF ALIGNMENT.
 - (B) SHIP-SPECIFIC.
 - (C) DOCUMENTED ON CSMP PRIOR. FWD EFP WAS SAT.
 - (D) N/A

B. DAMAGE CONTROL

- (1) FIREFIGHTING/FLOODING
- ONLY SINGLE RELEASE HALON SYSTEM PROVIDED IN PROPULSION SPACES.
- (A) SHIP IS NOT PROVIDED WITH A SECOND BANK OF HALON BOTTLES IN EVENT OF FIRE REFLASH.
 - (B) CLASS PROBLEM.
 - (C) N/A

(CLASSIFIED MARKINGS FOR ILLUSTRATION PURPOSES ONLY)

COMPHIBGRUTHREEINST 4730.1C

	(D)	N/A	
DECL			
BT			

(CLASSIFIED MARKINGS FOR ILLUSTRATION PURPOSES ONLY)